

APPENDIX C – PHOTOGRAPHIC OVERVIEW

Existing Water System Condition



Forest Road 50079



Curve/Switchback



Hazard Tree Fallen from Cut Bank



Pipeline Crossing



Hazard Tree Felled by Wind



Hazard Trees in Road Surface



Cattleguard – MWS Boundary



Unclassified Road



Terracing Above FR 50079

Vegetation



Spruce Beetle Killed Tree



Aspen Clone



North Creek



Aspen/Spruce-fir Stand



**Upper North Creek
Spruce Beetle Killed Trees**



**Upper Indian Creek
Conifer Encroachment in Aspen**

(This page intentionally left blank)